



Communication	Navigation	Services
CTAF ..... 122.7 APP/DEP ..... 135.45 FSS ..... 122.1R 117.0T	<b>Elevation ..... 825'</b> <b>TPA ..... 1825'</b>  VOR to Field: 117.0 DLL 084°/12 NM	<b>FUEL: MOGAS, 100LL</b> <b>24 HR Self-Serve</b>  <b>Air Portage</b> <b>608-742-3300</b>
<p><b>NOTES:</b> 1. Large buildings and trees beside runway 35 causes wind shear with strong northwest winds.                      2. 110' power lines located 1580' south of runway 35                      3. Runway 04-22 closed Nov. 15 to Apr. 15.</p>		